



CONTROLLER PIN OUT

TAB	FUNCTION
1	KSI VOLTAGE
2	THROTTLE
3	THROTTLE
4	1/2 SPEED REVERSE
B+	BATTERY POSITIVE
B-	BATTERY NEGATIVE
M-	MOTOR MINUS

NOTES:

- * FUSES REQUIRED FOR ALL INSTALLATIONS
- * DIODE REQUIRED ACROSS COILS / RELAYS
- * PRE-CHARGE RESISTOR REQUIRED
- * ASSUMES FOOTSWITCH IS OPEN WHEN THROTTLE OFF
- > ALLTRAX RESERVES THE RIGHT TO CHANGE DOCUMENTATION WITHOUT NOTICE
- * ALLTRAX MAKES NO WARRANTY AS TO THE ACCURACY, SUFFICIENCY, OR SUITABILITY OF ANY TECHNICAL OR OTHER INFORMATION PROVIDED
- > SEE OPERATORS MANUAL FOR MORE INFORMATION

REVISIONS			DWG SCALE: NTS		PROPERTY	
REV.	ECO.	DATE	APVD	DRAWN	T.Thorne	121806
A		010407	TT	ENGR	D.Crockett	121806

THIS DRAWING IS THE PROPERTY OF ALLTRAX. IT IS TO BE USED IN WHOLE OR IN PART WITHOUT WRITTEN PERMISSION OF ALLTRAX INC.

TITLE	AXE-Taylor Dunn
Wiring Diagram	
SIZE	DOCUMENT NO.
A	S Doc100-049
REV.	A
FILE:	_DWG-AXE-Taylor-Dunn-wire-dwg
SHEET	1to1

DO NOT SCALE DRAWING

1111 Cheney Creek Rd.
Grant's Pass, OR 97527
PHONE:(541) 476-5565